



SR Model Wiring Diagram

Part # 305052 and 348524



	L1018	L1030	L1040	L1050
Serial Numbers	From : 1000183	1010365	All	1020282
	To : Present	Present		Present



	L1018	L1030	L1050
Serial Numbers	From : 1000001	1010001	102001
	To : 1000182	1010364	1020281

Rev 1-0