

PARTS ILLUSTRATION

SOFT START MOTOR STARTER BOX ASSEMBLY

REF. No.	PART No.	DESCRIPTION	No. REQD.
1	17721-11	SERVICE CORD	1
2	16591-1	CONDUIT CONNECTOR	1
3	35016-1	CONNECTOR w/BACKET	2
4	35572	10 AMP FUSE for 1/2hp converter	2
	35573	20 AMP FUSE for 1hp converter	
5	24261-1	MARKER STRIP	1
6	24260-6	TERMINAL STRIP	1
7	35569	1/2 HP. CONVERTER	1
	35570	1 HP. CONVERTER	1
8	35571	FUSE BLOCK	1
9	32506	MINI LOUVER/VENT	4

